



WELDING Safety Tips

WHEN SPARKS FLY, EXERCISE CARE AND CAUTION.
SO WE ALL GO HOME SAFE!

Look around

Make sure there's **no clutter** in your workspace. This includes work surface, floor and unnecessary equipment in surrounding area.

Wear **Personal Protection Equipment**, including safety coverings, gloves, footwear. Don't wear polyester, nylon or tattered clothing, ever!

Use proper PPE

Expect heat

Assume all metal in the welding environment is **HOT and act accordingly**. Make sure all others around you are aware and safe, too!

From operating to maintaining the tools, be sure **you know the correct use** and storage of the equipment you're using. Read the manuals!

Get training

Be ready

Always have a **fire extinguisher** within reach so you're prepared if something goes wrong. Also, know the location of the fire alarm.